

Mass Spec Protocol for GxTx-13ACM

- 1.) Load the Xcalibur software window, and check the following settings,
 sheath gas:
 aux gas:
 Indicator's OK:
- 2.) Using the 500uL Hamilton syringe, wash with 50% MeOH, prior to injecting any samples. Then, load your syringe with 500uL, of the desired solvent solution that does not contain your sample.
- 3.) Load the syringe into the tubing